Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: RONALD DEAN 17-20H

Field Name: STANLEY Well File #: 18568

Date Incident: 4/2/2015 Time Incident: 13:00 Facility ID Number:

County: MOUNTRAIL Twp: 155 Rng: 91 Sec: 17 Qtr: NW NW

Location Description:

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 10 Barrels 5 Barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Oil misting on grass in field immediately adjacent field

Potential Environmental Impacts:

Minimal. No waterways or wetlands in immediate area.

Action Taken or Planned:

The well was shut in. Repairs to gasket will be completed. The impacted area will me mowed and contaminated grass will be disposed. Vacuum truck recovered oil on site. Bio-remediation will be applied to the facility soil.

Wastes Disposal Location: recover oil in production tank. Solids to PDI.

Agencies Involved:

Updates

Date: 4/3/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

4/3/2015 at 10:49, on location. Spray occurred out of treater located in SW corner of wellpad, impacting two fields to the south and southeast. Approximate extent is 500 feet based on aerial photography of the area. Impacted fields are occupied by various grasses. There are no water features or standing water visible in the area. Impact appears limited to vegetation. Call made to report contact. Contact will be meeting with landowner of field to the southeast; this landowner also may own the field directly south of the treater.

Date: 4/5/2015 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, impacted vegetation and soil adjacent to the well pad according to the report. Followup is necessary.

Date: 4/6/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 18:26 4/6/2015.

Cleanup is ongoing at the location. Spray out into field, with the heaviest impact right next to the well lease.

Contact company requesting cleanup confirmation samples.

Date: 6/8/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 4:44 6/8/2015.

Some residual oil present off of location to the south in the corner of the agricultural field. Contact with company will be made to ensure proper cleanup.

More follow up is necessary.

Date: 9/1/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:37 9/1/2015.

Residual oil-stained material in northeast corner of adjacent wheat field to the southwest. Dead area with no vegetation roughly 10 yds by 15 yds.

More followup is necessary to ensure proper cleanup.